



Number	G9-2
Score	216 / 487
Rank	11位


部品実装割合




減点ポイント(不良例)



取付方向相違
IPC-A-610G 7.1.1.1を参照



はんだ不足
IPC-A-610G 8.3.14, 8.3.5を参照



はんだ過多
IPC-A-610G 8.3.2を参照



FOD
IPC-A-610G 10.6.2を参照